

Fractionner un mélange

Logiciel PAINTMANAGER® XI

Les couches Sous-couche (Undercoat), Couleur (Color) et Transparence (Clearcoat) peuvent être fractionnées en plusieurs tâches. Le fractionnement peut être exécuté à l'écran Sommaire du mélange (Mix Summary) durant le mélange ou à l'écran Couches (Layers) de la tâche après le mélange.

À l'écran Sommaire du mélange (Mix Summary)

Split Mix

1

ou

Sur le menu des outils de l'écran Couches (Layers) de la tâche

Split Mix

2

Sélectionnez les tâches

ou

3

Cherchez les tâches

Une fois une tâche trouvée, effacez la recherche et cherchez une autre tâche

4

Suivant (Next)

5

Entrez le montant à fractionner

ou

6

Pesez le produit

7

Supprimez les tâches, au besoin

8

Suivant (Next)

9

Terminer (Finish)

Step 1: Select jobs to be used for splitting the mix. Next Cancel

3 RO Number Search for Jobs 4 X

<input type="checkbox"/>	RO#	CUSTOMER	VEHICLE	PRIORITY	DUE DATE
<input type="checkbox"/>	1002	Customer 2	2013 Ford F150	Normal	
<input checked="" type="checkbox"/>	1003	Customer 3	2009 Subaru Outback	Normal	
<input type="checkbox"/>	1005	Cu	Hyundai Sante Fe	Normal	
<input checked="" type="checkbox"/>	1006	Cu	Mazda Mazda3	Normal	
<input type="checkbox"/>	1008	Customer 8	2015 Chrysler Journey	Normal	

2 Select one or more Jobs

Clear search to start an additional search.

Step 2: Verify the amounts to be applied to each job. Next Cancel

8 Note total available → Available Amount 30 floz

1003 X

5 - 10 + U.S. Fluid Ounces Weigh

1006 7 X

Enter amount to split

Note total split → Total Poured 20 floz 6

Step 3: Finish

Remaining Amount 10.0 floz

9 Finish